



Fisa tehnica

Caracteristica	valoare
Eroare de linearitate	$\pm 2\%$ FS, valoare de referinta 5 - 70% Tip. $\pm 3\%$ FS, 70 - 95% valoare nominala fata de curba caracteristica ideala
Histerezis	1,5%, valoare de referinta 5 - 70% Tip. 3%, 70 - 95% valoare de referinta
Raspunsul la sensibilitate	1,5 %FS
Precizie generala	typ. 3 %FS
Acuratete de repetitie in \pm %FS	1,5 %FS