## Fluid connector set

SASA-FW-A-100-TG34 Part number: 8036893 Product to be discontinued Type to be discontinued. Available until 2022. See Support Portal for alternative products.



## **Data sheet**

Feature	Value
Corrosion resistance classification CRC	3 - High corrosion stress
Materials note	Conforms to RoHS

**FESTO**