Fluid connector set SASA-FW-A-32-TR34 Part number: 8036896 Product to be discontinued

Type to be discontinued. Available until 2022. See Support Portal for alternative products.





Data sheet

Feature	Value
Corrosion resistance classification CRC	3 - High corrosion stress
Materials note	Conforms to RoHS