

Multiple Distributors

Multiple distributors with one common air supply and 2 to 6 outlets are assembled as required, using an appropriate hollow bolt and 2 or 3 distributor ring pieces.

Multiple Distributor

With Female Thread, consisting of

Hollow Bolt, Type VT-...

With Male Thread

and

Distributor Ring Pieces

Type LK-... one outlet

TK-... two outlets

With Female Thread

With Female Threads
Type LK-...



Type TK-...



Type VT-...



Shown assembled

Tube Connections	Hollow Bolt					Distributor Ring Piece				
	Supply	No. of Distributors	Order Number		Material	Weight lb / kg	Order Number		Material	Weight lb / kg
			Part No.	Type			Part No.	Type		
Female Thread, Without Connectors	G 1/8 ISO	2	206146	VT-1/8-2	Steel, galvanized	0.046 / 0.021	9181	LK-1/8	Diecast Zinc with 2 Gaskets	0.013 / 0.006
		3	004596	VT-1/8-3		0.059 / 0.027	9182	TK-1/8		0.018 / 0.008
Female Thread, Without Connectors	G 1/4 ISO	2	009177	VT-1/4-2-1/4		0.079 / 0.036	9173	LK-1/4		0.033 / 0.015
		3	009596	VT-1/4-3-1/4		0.097 / 0.044	9174	TK-1/4		0.044 / 0.020
Female Thread, Without Connectors	G 3/8 ISO	2	009179	VT-3/8-2-3/8		0.101 / 0.046	9175	LK-3/8		0.044 / 0.020
		3	009180	VT-3/8-3-3/8		0.123 / 0.056	9176	TK-3/8		0.055 / 0.025

*With integral sealing surface.
Pressure range 0 to 150 psi / 0 to 10 bar
Temperature range 14 to 140°F / -10 to +60°C