

## Safety component

This pneumatic start block is used where a manually-started operation, such as the triggering of compressed air cylinders, would otherwise involve danger for a machine operator, or with other devices where regulations require that machine operators have both hands clear of a danger zone when starting a machine.

A continuous signal will be present at the output A only if pressure is applied via 3/2-way pushbutton valves to the two valve inputs p1 and p2 simultaneously, within 0.2 to 0.5 seconds.

If one or both of the pushbutton valves are released, flow to the output is immediately interrupted and any cylinders or valves connected to output A are reversed.

This start block is a safety component as defined by EU Machinery Directive

89/392/EU, Appendix 4, and is CE-certified.

It falls within Category 1 as defined by EN 954 (only in conjunction with a pressure sequence valve such as VD-3-PK-3) and conforms to Type III A as defined by EN 574.


## Control block for two-hand start ZSB

Technical data

Technical data		
Operating medium		Filtered compressed air, lubricated
Constructional design		Poppet valve
Nominal size	[mm]	4
Standard nominal flow rate	[l/min]	>50
1 > 2		
Input pressure	[bar]	38
Temperature range	[°C]	-10 +60
Pneumatic connection		G1/8
Type of mounting		Mounting thread
		Through-holes in housing
Mounting position		Any
Materials		Housing: anodised aluminium; seals: nitrile rubber
CE mark (see declaration of conformity)		In accordance with EC machinery directive
Weight	[g]	490

## Sample circuit diagram

Showing positioning and hand valves for setting operations



## Note

When installing the two pushbutton valves which actuate the start block, make sure that the protective function cannot easily be defeated, for example by pressing the pushbutton valves with the hand and elbow of the same arm. If necessary, the pushbuttons valves should be fitted with an additional guard

